





316

Project Resources Inc.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 784		
Property Address: 3401 Race 5t.	,	
Owner: Johnnie Peters, Merriel Scroggi	ns, Sharon Bridge	e-forth
Phone: 303-344-5261 JOINNE 1	afect.	<u></u>
L SOS STI SANT OVINGIAL VI		
Restoration Items in Question:	·	
		·····
Item:		
Item:		
	<u> </u>	
item:		
Item:		
Item:	,	1
Item:		
	<u></u>	
Additional Comments:		
Additional Comments.	,	
	•	
		j
·		
		
I agree restoration is completed, except as noted		
I do not agree restoration is completed .		
I agree that the sprinkler system is working properly following reinstallation by contractor		
	_	
Johnnie R. Reles	any James	5/14/05
Owner's Signature Date	Contractor's Signature	Date









U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Sharon Bridgeforth , Merriel Scroggins, Johnnie Peters
Property Address	3401 Race Street
Property Identification Number	784

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)		\$ 2.50	\$
Itemized plants		\$7.00	\$
Itemized shrubs/bushes	10	\$12.00	\$120.00
Total			\$120.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$120.00 has been received by the owner in the form of a replacement certificate, # 14 \$56, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date

Contractor's Signature

Date





Real Property Records

Date last updated: Friday, November 26, 2004

3 Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Commercial

Name and Address Information

BRIDGEFORTH, SHARON &

SCROGGINS, MERRIEL

1727 E 38TH AVE

DENVER, CO 80205

Parcel: 0226113009000

Legal Description

L 14 & 15 BLK 16

CHEESMAN & MOFFATS ADD

RESIDENTIAL DUPLEX

Property Address:

Tax District

DENV

3401 RACE ST

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	31300	2490		
Improvements	172600	13740		
Total	203900	16230	0	16230
Prior Year				
Land	31300	2490		
Improvements	172600	13740		
Total	203900	16230	0	16230

Style: Other

Year Built: 1916

Building Sqr. Foot: 1,989

Bedrooms:

Baths Full/Half: 0/0

Basement/Finished: 0/0

Lot Size: 6,930

Zoning: R2

Reception No.: JT00240719

Recording Date: 11/17/03

Document Type: Quit Claim

Sale Price: 10

Mill Levy: 64.162

Meagan Redfern

From:

OCARS_Pro@uncc.org

Sent:

Thursday, March 31, 2005 3:07 PM

To:

Meagan Redfern

Subject:

UNCC EMLCFM 2005/03/31 #00296 B0001450-00B NORM NEW

EMLCFM 00296 UNCCb 03/31/05 03:06 PM B0001450-00B NORM NEW STRT LREQ

Ticket Nbr: B0001450-00B

Original Call Date: 03/31/05 Time: 03:06 PM Op: MRE

Locate By Date : 04/04/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER Addr: 3401 Street: RACE ST City:

Grids: 03S068W26NE Legal: N :

Lat/Long: 39.766386/-104.964307 39.766386/-104.962522

: 39.763814/-104.964307 39.763814/-104.962522

Type of Work: SOIL EXCAVATION TO A DEPTH OF 12 INCHES

Boring: N

Location: LOC ENTIRE LOT* ACCESS OPEN* ENTIRE PROPERTY FROM CURB

INCLUDES CITY

: PROPERTY

Company: PROJECT RESOURCES INC.

Type: OTHR

Caller : MEAGAN REDFERN

Phone: (303)487-0377

Alt Cont: AMY JAMES

Phone: (303) 487-0377

Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: ARMY CORPS OF ENGINEERS/EPA

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA ATCT01 = AT&T

Members CMSND00= COMCAST - NORTH DENVER PCNDU0 = XCEL ENERGY-NORTH

DENVER

Members PSND14 = XCEL ENGY--APPT SCHEDULE-- U QLNCND0= QWEST LOCAL

NETWORK (UQ)

Members QLNCND1= QWEST LOCAL NETWORK WCG01 = WILTEL

COMMUNICATION

You are responsible for contacting any other utilities that are not listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303) 628-6666 DNVPR1 DENVER PARKS & REC. (303) 458-4839 DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001 WWMG01 WASTEWATER MGMT DIVISION (303) 446-3744



RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name:	Phone: 303-333-3290
Sharon Bridgeforth	, Merriel Scroggins 303-294-9/05
Addresses of	Address: 3401 Race St
Properties covered by	Address:
this Agreement:	Address:

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:



DERECHO A ENTRAR LA PROPIEDAD

Dueño/a de la Propiedad:

El otorgante (dueño/a de la propiedad) le da permiso y autoriza la Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) y/o a sus representantes autorizados (Cesionario) a entrar y a llevar a cabo algunas actividades ambientales en la propiedad a continuación:

Sharon Bridgefort Scroggins	Número de Teléfono:			
Dirección de las	Dirección:	3401 Race St		
Propiedades Cubiertas por este	Dirección:		-	
Acuerdo:	Dirección:			

PROPÓSITO DE LAS ACTIVIDADES AMBIENTALES

La EPA solicita el acceso a tomar muestras de tierra y a remover la tierra en su propiedad que tiene concentraciones altas de arsénico y/o plomo que podrían ser peligrosos a su salud. La tierra será removida y el(las) área(s) excavada(s) serán reemplazadas con materiales limpios. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de la EPA contactará al Otorgante personalmente para discutir el trabajo que se va a realizar en la propiedad del Otorgante. El Otorgante tendrá la oportunidad de examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termine, el Otorgante revisará el trabajo, confirmará su terminación y cumplirá con su aprobación. Después de la terminación del trabajo, el Otorgante recibirá un documento escrito por la EPA que indicará que la propiedad ha sido remediada.

ACCIONES DE LA ACTIVIDAD AMBIENTAL

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractores y subcontractores el derecho a entrar la propiedad, en tiempos razonables y sin noticia anterior, para el único propósito a realizar el trabajo aquí descrito. Este acceso debería persistir en efecto hasta que el trabajo haya sido terminado. El Ortogante también está de acuerdo con:


- Remove obstructions Página 1 of 2 vehicles, playscape items, etc;
 including boats, trailers, wood piles, dog houses,
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

I grant access to my properties	☐ I do not grant access to n	ay properties
Sharon R. Brickastot 10/18/64 Signature Date	Signature	Date
☐ I would like to be present during any sampling th☐ My property has a working sprinkler system that	-	,
-		



- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

Si, yo permito acceso a mi propiedad.		☐ No permito acc	No permito acceso a mi propiedad.		
		en e	er er er er er er er er er		
Firma	Fecha	Firma	Fecha		
☐ Me gustaría ser	presente durante de cualqui	er colección de muestras.			
Mi propiedad tid	ene un sistema de regar plan	tas y sacate (sprinkler syste	em).		

ledu 0 100 Can remove DG. man 24136 : 864 Tru 0 from's mild DC Q2 X) : 322 (an remae Stump Brow mulch 24×28: 672 4x122-488 Save flagstone break world Lg. Rak TACC ST. 3401 \$ 10 Koch | 36x24=864 \$ >x > _ 5 28 Lg. Rock 1420:280 15×25 = 770 from, Lg nock shrubs in by shrubs DISPUSE OF All ties. [] 2×2=4



Property Access Checklist

Property ID: 784	~		(STARTED ON:/_/_	
Property Address: 3401 Ran			COMPELTED ON:/_/_	
• 4				_
Property Owner: Sharon Bridge	portins	Property R	lenter:	
Mailing Address:	, 0	Home Pho	ne:]
1727 E.38th	• •	Fax:]
Denver. CO 8020.		Cell/Pager:		ļ
Home Phone: 303 - 333 - 329		Additional	Information:	
Fax: fax 303- 294-6 Cell/Pager:	1105-4			ĺ
	· · · · · · · · · · · · · · · · · · ·			ļ
Peters (203344-526)	T	ct he,		1
Notification Letter	+	<u> 104 104 </u>	By: A.James	1
Access Agreement	·	7/12/04	By: Sharon Bridge forth	þ
Restoration Agreement	Signed: 12	<u> ハ </u>	By: Johnnie Peters	
Topsoil Sampling (if applicable)			Ву:	
Disposal Sampling (if applicable)	/_	_'	By:	
Garden Sampling (if applicable)		_'	By:	
Utility Clearance	Called:	<u> </u>	By:	
Video/Photos (Before)	On: 12/	TTIOH	By: myers - video Lynch	·p L
☐ Video/Photos (During)	On:/	/	By:	
☐ Video/Photos (After)	On:/		By:	
☐ Video/Photos (30-Day)	On:/	/	Ву:	
Property Completion Agreement	Signed:	//	By:	
☐ Final Report	Issued:	//	Ву:	
Air Maritanine (or anti-akta)				
Air Monitoring (as applicable) Community Crew On:	_//_	By:	<u> </u>	1
Results:	<u>-''</u>			
		T		
	_//	By:		
Results:				
Community Crew On:	_//	By:		
Results:				



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 784	
Property Address: 3401 Race 5+.	
Owner: Sharon Bridge-Forth a	Merriel Scroggins
Phone: 303 -333 -3290	\mathcal{U}

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

item:							
	Any	(0/5	i	Dac	king	10+	
Item:				1-29			
				(
Marrie							
item:							
Item:							
							
Item:							
Item:							
108111.						•	
Item:				<u> </u>			
Item:							



Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item: wood tie borders in front
wood the Bolders in tront
l House
tem: Flagstone walk along side them: OF house
Item:
of house
Item:
See sketch
Item:
Item:
item.
Busues in front
Item:
Home To De Demoved Dy Continues and Dynam Demodiation And Deviced
Items To Be Removed By Contractor During Remediation And Replaced

Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)

Item:	
	Any fences
Item:	
Item:	
l	



Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	·	Square Feet	
Number of trees > 2 inch trunk diameter	フ		
Number of trees < 2 inch trunk diameter	P		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	NA		Zones:
Number of and total size of all gardens / flower beds. Attach a sketch of relative sizes and locations.	# Of Beds: # Of Gardens:		Ft ² Of Beds: Ft ² Of Gardens:



Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	NA	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	·	SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Fr²:	SF	Sod: Brown Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:

Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large: Medium: Small (pea gravel): Driveway Gravel:
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover:		

Additional Comments / Instructions:

Deal with Journil Peters
with any questions on
Property. Sue is the
house chair person (303) 344-5261

Can also deal with
merriel seroggins at
(303) 333-3290



Additional Comments / Instructions Continued.
Ladies would like
information on
Sineone who can
Keri signe the property
j
Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.
✓ I agree ☐ I do not agree ☐ I do not agree
Owner's Signature Date Date Contractor's Signature Date








VB/I-70 Command Post 10 E. 55th Avenue Denver, CO 80216

80216+1769 ii



1)	784-001	- DWC	0850 hours	06/03/06
	784 002			06 /03/06
			0910 hours	06 /03/06
	784 - 002		0905 hours	06/03/06
,				
6)				

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 784-001-DWC Client Project ID: 213001.01 Date Collected: 6/3/06 Date Received: 6/5/06

Lab Work Order: 06-3491 Lab Sample ID: 06-3491-05 Sample Matrix: Wipe

METALS

Method: SW6010 Prep Method: SW6010

Dilution Factor: 1 Date Prepared: 6/9/06 Lab File ID: 061206PM

Date Analyzed: 6/13/06 Method Blank: MB-10113 Lab Fraction ID: 06-3491-05A

Analytes **CAS Number** Result LQL Units 7439-92-1 U Lead 4.0 μg/WIPE

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Print Date: 6/13/06

Definitions: NA - Not Applicable

Approved

LQL - Lower Quantitation Limit

Surr - Surrogate

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 784-002-DWC Client Project ID: 213001.01 Date Collected: 6/3/06 Date Received: 6/5/06

Lab Work Order: 06-3491 Lab Sample ID: 06-3491-06 Sample Matrix: Wipe

METALS

Method: SW6010 Prep Method: SW6010

Date Prepared: 6/9/06 Lab File ID: 061206PM Dilution Factor: 1

Date Analyzed: 6/13/06 Method Blank: MB-10113 Lab Fraction ID: 06-3491-06A

Analytes CAS Number Result LQL Units

Lead 7439-92-1 U 4.0 μg/WIPE

Analyst

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/13/06

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 784-001-SCC Client Project ID: 213001.01 Date Collected:

6/3/06 6/5/06 Lab Work Order: 06-3491

Lab Sample ID: 06-3491-07 Sample Matrix:

Soil

METALS

Method: SW6010 Date Prepared: 6/7/06

Date Analyzed: 6/9/06

Lab File ID:

060806PM

Prep Method: SW3050 **Dilution Factor:**

Lab Fraction ID: 06-3491-07A

Analytes

Date Received:

Method Blank: MB-10099 **CAS Number**

Result

LQL

Units

Lead

7439-92-1

22

5.9

mg/Kg

Analyst

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Print Date: 6/13/06

Definitions: NA - Not Applicable

Surr - Surrogate

LQL - Lower Quantitation Limit

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 784-002-SCC Client Project ID: 213001.01 **Date Collected:** 6/3/06 Date Received: 6/5/06

Lab Work Order: 06-3491 06-3491-08 Lab Sample ID: Sample Matrix: Soil

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 6/7/06 Lab File ID: 060806PM **Dilution Factor:**

Date Analyzed: 6/9/06 Method Blank: MB-10099 Lab Fraction ID: 06-3491-08A

Analytes CAS Number Result Units LQL Lead 7439-92-1 21 5.4 mg/Kg

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.


Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/13/06



1)	78	4-001	- DWC	- 0850 hours	06/03/06
				0855hours	06 /03/06
				0910 hours	66 /03/06
			_	0905 hours	06/03/06
5)					
6)					

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3401 Race St.


C

INPUTS General	Variable Mixing depth in yard Mixing depth in yard Soil density RBC in soil Bkg in clean fill	Units cm inches g/cm3 mg/kg mg/kg	House 2:54 1 2:5 400 50 Small
House-specific	Area of the exposure unit Area of the exposure unit Concentration of lead in paint Area of peeling paint Area of peeling paint	m2 ft2 mg/cm2 m2 ft2	111 4836 1200 11 90 21907 971 11
COMPUTATIONS	Mass of lead from paint Volume of soil Mass of soil Incremental concentration Maximum acceptable area of p Maximum acceptable area of p		9.9E+06 2.8E+06 7.1E+03 1401.9 22.5 242.4
DECISION			Not OK

Address:	3401 Race St.				8/10/2005			
Owner:	Sharon Bridgeforth and	Merrill So	croagins		Telephone #:	(303) 33:	3-3290	
JWIIEI.	land	I WEITH OC	Joggins		reiephone w.	(000) 00	0 0200	
Plot Plan:								
_								
					•			
						0	a list	
						Poo	ho had in	
						•	p.rdy# 184	
				1		_	14/4	
		:	see attached			/	0 '	
								•
								· · ·
		Exterior Wa	lls			Doors/		
		Exterior Wa	lls			Doors/I	<u>Frim</u>	
	Material	Exterior Wa deteriorated Area	Ils Peel/Chip	XRF (Lead)	Material	Doors/ deteriorated Area		XRF (Lead)
North	Material	deteriorated		XRF (Lead)	Material	deteriorated		XRF (Lead)
South	Material	deteriorated		XRF (Lead)	Material	deteriorated		XRF (Lead)
South East	Material	deteriorated		XRF (Lead)	Material	deteriorated		XRF (Lead)
South		deteriorated Area		XRF (Lead)		deteriorated Area		XRF (Lead)
South East	Material Total	deteriorated		XRF (Lead)	Material Total	deteriorated		XRF (Lead)
South East	Total	deteriorated Area 0.00 ndow Trim/Fas	Peel/Chip	XRF (Lead)		deteriorated Area 0.00 Patios/Decks	Peel/Chip	XRF (Lead)
South East	Total	0.00 ndow Trim/Fast deteriorated	Peel/Chip		Total	0.00 Patios/Decks	Peel/Chip	
South East West	Total Wir	0.00 ndow Trim/Fast deteriorated Area	Peel/Chip	XRF (Lead)		deteriorated Area 0.00 Patios/Decks	Peel/Chip	XRF (Lead) XRF (Lead)
South East West	Total Wir Material wood	0.00 ndow Trim/Fas deteriorated Area 373.92	Peel/Chip	XRF (Lead)	Total	0.00 Patios/Decks	Peel/Chip	
South East West North South	Total Wir Material wood wood	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10	Peel/Chip	XRF (Lead) 11+-3	Total Material	0.00 Patios/Decks deteriorated Area	Peel/Chip	XRF (Lead)
South East West	Total Wir Material wood	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10	Peel/Chip	XRF (Lead)	Total	0.00 Patios/Decks	Peel/Chip	
South East West North South East	Total Wir Material wood wood wood	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10	Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material	0.00 Patios/Decks deteriorated Area	Peel/Chip	XRF (Lead)
South East West North South East	Total Wir Material wood wood wood wood Total	0.00 ndow Trim/Fas deteriorated Area 373.92 91.10 119.10 181.27 765.39	Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood	0.00 Patios/Decks deteriorated Area 205.72	Peel/Chip	XRF (Lead)
South East West North South East	Total Wir Material wood wood wood wood Total	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39	Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood	0.00 Patios/Decks deteriorated Area 205.72 Structures/Co	Peel/Chip	XRF (Lead)
South East West North South East	Total Wir Material wood wood wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39 Trim/Gutters/E deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood Total Mis	0.00 Patios/Decks deteriorated Area 205.72 c Structures/C deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead)
South East West North South East West	Total Wir Material wood wood wood wood Total	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39	Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood	0.00 Patios/Decks deteriorated Area 205.72 Structures/Co	Peel/Chip	XRF (Lead)
South East West North South East	Total Wir Material wood wood wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39 Trim/Gutters/E deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood Total Mis	0.00 Patios/Decks deteriorated Area 205.72 c Structures/C deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead)
South East West North South East West	Total Wir Material wood wood wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39 Trim/Gutters/E deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood Total Mis	0.00 Patios/Decks deteriorated Area 205.72 c Structures/C deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead)
South East West North South East West North South East	Total Wir Material wood wood wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39 Trim/Gutters/E deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood Total Mis	0.00 Patios/Decks deteriorated Area 205.72 c Structures/C deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead)
South East West North South East West North South	Total Wir Material wood wood wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 373.92 91.10 119.10 181.27 765.39 Trim/Gutters/E deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 11+-3 11+-3 11+-3	Total Material wood Total Mis	0.00 Patios/Decks deteriorated Area 205.72 c Structures/C deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead)

.

(26+12)(62+12) - (26×62) (38) (74) - 1612 2812-1612 - 1200



340/ Race

3401 Race St.		Structure:	House								
8/10/2005		Direction:	East								
CM & WH											
9;15 a.m.											
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element (units ft^2)	Percent Deteriorated	Deteriorated Area (units ft^2)	XRF#	XRF Value	Dos/neg	Notes
Didwing Manibol	- Italipei	T diffica outlase	Material	00.01	(dilles it 2)	Beterioratea	1. 2,	7	7.1.1. 14.45	Foomeg	(100)
		Front Porch Steps	Concrete	Red	n/a	n/a	n/a	154	0.03±0.14	Neg.	
1	1	Front Porch Beam	Wood	White	84.67	50%	42.33	155	11 + - 3.0	Pos.	
		Front Porch									
2	2	Window Frames	Wood	White	1.06	10%	0.11	156	10 +- 2.9	Pos.	
3	3	Front Porch Soffit	Wood	White	63.50	100%	63.50	See 155	11 + - 3.0	Pos.	
		Front Porch									
4	4	Rafters Tails	Wood	White	56.00	100%	56.00		11 + - 3.0		'
5	5	Domer Soffit/Trim	Wood	White	119.10	100%	119.10	See 155	11 + - 3.0	Pos.	
		Front Porch					_				
19		Ceiling	Wood	White	218.92	20%	43.78	165	0.9 + - 0.2	Pos.	
3401 Race St.	1		House			<u> </u>			L	 	
8/10/2005		Direction:	South								
CM & WH							;			i	<u> </u>
9;15 a.m.							i		ļ <u>.</u>		
							<u> </u>		<u> </u>		
	Photo				Total Area of Element	Percent	Deteriorated Area (units			} ;	i
Drawing Number	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated	ft^2)	XRF#	XRF Value	pos/neg	Notes
6	6	Gable Trim & Soffit	Wood	White	167.87	50%	83.93	See 157	27±4.4	Pos.	
		Upper Window		T				<u> </u>			
7	6	Trim		White _		n/a	2.67			Pos	
			Wood	White	n/a	n/a	28.66	158	0.00+-0.07	neg	
		Basement window									
8	7		Wood	White	n/a	n/a	0.50	See 156	10±2.9	Pos.	
		Main window									
9	7	frames	wood	White	n/a	n/a	4.00	See 156	10±2.9	Pos.	1

		Structure:	House								
3401 Race St.		Direction:	West								
8/10/2005											
CM & WH											
	Dhata				Total Area of	1	Deteriorated				
0.45	Photo				Element	Percent	Area (units	V5= "	VDE 14.1	1.	January
9;15 a.m.	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated	ft^2)	XRF#	XRF Value	pos/neg	Notes
		Dormer soffit &							1	_	I į
10	9	trim	Wood	White	60.84	100%	60.84	See 155	11 +- 3.0	Pos.	
l)	Lower soffit &			J	1	J		1	_	
11	10	rafter tails (22)	Wood	White	111.67	100%	111.67		11 + - 3.0		1
12	11	Window frame	Wood	White			1.77	See 159		Pos.	<u> </u>
13	12	Door Frame	Wood	White			3.33	See 159	10 +- 2.7	Pos.	
		Basement window								i	
14	13	cover	Wood	White	7.32	50%	3.66	160	2.1 + - 0.8	Pos.	1
3401 Race St.		Structure:	House	}	1		1	1	i	1	
8/10/2005			North	 	- 		 	1	1	+	
CM & WH				1		[1	
9;15 a.m.	<u> </u>			1			<u> </u>	<u> </u>	† · · · · · · · · · · · · · · · · · · ·	· · -	
	Photo				Total Area of Element	Percent	Deteriorated Area (units			!	
Drawing Number	Number	Painted Surface	Material	Color	I	Deteriorated	ft^2)	XRF#	XRF Value	pos/neg	Notes
15	14	Gable trim & soffit	Wood	White	360.00	100%	360.00	See 157	27 + - 4.4		
		Soffit support					<u> </u>		1	+	
16	15		Wood	White	10.67	100%	10.67	¹ 157	27 + - 4.4	Pos.	1
		Basement window		1	-		1	1	,		
17	16		Wood	White	1	i	0.92	161	41 + - 13	Pos.	
		Main level window			1	-	+	1	1		
18	17		Wood	White	1	1	2.33	0 404	41 + - 13	·	

• • •

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1049104

	500	OMERT ROMBER.
SI	TE NAME:	VASQUEZ BOULEVARD AND I-70
DO	DCUMENT DATE:	06/03/2006
Dι	ue to one of the fol	DOCUMENT NOT SCANNED lowing reasons:
	PHOTOGRAPHS	
	3-DIMENSIONAL	
	OVERSIZED	
V	AUDIO/VISUAL	
	PERMANENTLY I	BOUND DOCUMENTS
	POOR LEGIBILIT	Y
	OTHER	
	NOT AVAILABLE	
		MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DC	OCUMENT DESCR	IPTION:
	3 - DVDs OF PRO	PERTY VIDEO, PROPERTY #784